

Office of the Assistant Executive Engineer,
PWD Buildings Sub Division, Kanhangad
Phone No. 0467-2200088
Email Id: aeebuildings8@gmail.com
Date : 24/05/2021

No. D3-Fit/10/2021

From

The Assistant Executive Engineer

To

The Principal
Kendriya Vidyalaya,
Kanhangad.

Sir,

Sub : Inspection of Kendriya Vidyalaya Building at Kanhangad-Report Submitting- Reg.
Ref : 1) Your Letter No. F.31373 (1-79)/KVKNGD/2021-22 dated 20/05/2021
2) Letter No. KS/24/2021-22 dated 24/05/2021 of the Assistant Engineer, PWD
Buildings Section, Kanhangad.

As per reference cited above, Kendriya Vidyalaya Kanhangad were inspected by the Assistant Engineer and report as follows.

- 1) Assistant Engineer inspected the two storied RCC framed building at the immediate left of the entrance gate at which the Kendriya Vidyalaya is functioning.
- 2) This building is found structurally fit for conducting classes under normal weather condition.
- 3) No repair/periodical maintenance works are not seen carried out in the building in the recent past. The same shall be carried out before commencement of classes.
- 4) The building number was not identifiable during inspection.

Report submitted for information and further necessary action.

Yours faithfully,



Assistant Executive Engineer

